MATERIAL SAFETY DATA SHEET

DATE: 11/06/01 Revision #2 Page 1 of 2

Section 1

PACER TECHNOLOGY 9420 Santa Anita Avenue Rancho Cucamonga, CA 91730 For Chemical Emergency Only:
In the US & Canada (800) 424-9300
Int'l & Wash DC (COLLECT) (202) 483-7616
Telephone for Information: (909) 987-0550

HAZARD RATING

PRODUCT IDENTIFICATION:

1 2 x 0

Super Glue Quick Setting Epoxy Resin (T-OS): Part A

Section 2 - HAZARDOUS INGREDIENTS INFORMATION:

Hazardous Components		OSHA	ACGIH	OTHER	%
(Common Names, CAS Number)		PEL PEL	TLV_	LIMITS	OPTION
Bisphenol A/Epichlorohydrin					
based epoxy resin	(25085-99-8)	NE	NE	NE	

Section 3 - PHYSICAL/CHEMICAL CHARACTERISTICS:

Boiling Point:NASpecific Gravity (H2O=1):1.17Vapor Density (Air=1):NAMelting Point:NAVapor Pressure (mm Hg):0.03 @ 25CEvaporation Rate (Butyl Acetate = 1):NA

Solubility in Water: Practically insoluble.

Appearance & Odor: Transparent viscous liquid.

Section 4 - FIRE AND EXPLOSION HAZARD DATA:

Flash Point (Method Used): 480F (TOC) Flammable Limits: LEL: NE UEL: NE

Extinguishing Media: Carbon dioxide, foam, or dry chemicals.

<u>Special Fire Fighting Procedures:</u> Do not enter confined fire space without full bunker gear (helmet/face shield, bunker coat, gloves & rubber boats). Use positive pressure NIOSH-approved self-contained breathing apparatus. Cool fire exposed containers with water.

<u>Unusual Fire and Explosion Hazards</u>: Closed containers may explode (due to buildup of pressure) when exposed to extreme heat.

Section 5 - REACTIVITY DATA:

Stability: Unstable__ Stable XX Conditions to Avoid: Keep away from open flames & high temperatures.

Incompatibility (Materials to Avoid): Strong acids, amines, mercaptans and bases.

<u>Hazardous Decomposition Products:</u> Carbon monoxide/dioxide, aldehydes, acids and other organic unidentified substances may be formed during combustion or elevated (>500F) temperature degradation.

Hazardous Polymerization: May Occur May Not Occur XX2

<u>Conditions to Avoid</u>: Run-a-way cure reactions may char and decompose the resin system, generating unidentified furnes and vapors which may be toxic.

Section 6 - HEALTH HAZARD DATA:

Route(s) of Entry: Inhalation: YES Skin: YES Ingestion: YES

Health Hazards (Acute and Chronic):

Product moderately irritating to eyes, skin; contact with product at elevated temperatures can result in thermal burns; may cause skin sensitization; low order of acute oral toxicity noted; unlikely to be inhalation hazard due to low volatility.

Super Glue Quick Setting Epoxy Resin (T-QS): Part A

Carcinogenicity:

NTP: No

IARC Monographs: No

OSHA Regulated: No

Signs and Symptoms of Exposure & First Aid Procedures:

Eye contact - irritation: flush eyes with copious amounts of water for 15 min. while holding eyes open Get medical attention immediately.

Skin contact - irritation/rash: remove contaminated clothing and wash with soap/water. Get medical attention if symptoms persist (contaminated leather articles i.e. shoes should be disposed of as contaminated waste). NOTE: hot product burns require immediate medical attention.

Inhalation - Remove to fresh air and provide oxygen if breathing is difficult. Get medical attention.

Ingestion - Do not induce vomiting. In general, no treatment unless large amount is ingested, however, get medical advice.

NOTE TO PHYSICIAN: Emesis induction is normally not necessary in high viscosity, low volatility products, e.g. neat epoxy resins.

Medical Conditions Generally Aggravated by Exposure: Pre-existing eye/skin disorders or lung allergies.

Section 7 - PRECAUTIONS FOR SAFE HANDLING AND USE:

<u>Steps to Be Taken in Case Material is Released or Spilled:</u> Product may burn although not readily ignitable. Use cautious judgment when cleaning up large spills. Respirator and protective equipment as appropriate. Dike and contain material. Soak up residue with absorbent (clay, sand) materials and dispose of properly.

<u>Waste Disposal Method</u>: If product becomes waste, not considered hazardous waste by RCRA criteria (40 CFR 261). Dispose of according to federal, state and local regulations.

<u>Precautions to Be Taken in Handling and Storing</u>: Store in cool, dry place away from open flames and high temperatures. Avoid direct contact. Wash thoroughly after handling. Avoid breathing vapors.

Other Precautions: Empty containers may contain product residues and should be disposed of properly.

Section 8 - CONTROL MEASURES:

Respiratory Protection (Specify Type): Organic vapor respirator in areas with poor ventilation.

<u>Ventilation:</u> Local Exhaust: Good Mechanical (General): As needed.

<u>Protective Clothing or Equipment</u>: Safety glasses/goggles with side shields, chemically resistant gloves and other protective equipment to avoid direct contact.

<u>Work/Hygienic Practices</u>: Avoid contact with eyes or skin. Use in well ventilated area. Wash hands with soap and water after product use. Launder contaminated clothing before reuse and dispose of leather articles as contaminated waste.

Section 9 - TRANSPORATION REQUIREMENTS:

D.O.T. Classification: Not regulated

D.O.T. Proper Shipping Name: Not regulated

Other Requirements: NA

NA = Not applicable NE = Not established

The data contained herein is based upon information that Pacer Technology believes to be reliable. Users of this product have the responsibility to determine the suitability of use and to adopt all necessary precautions to ensure the safety and protection of property and persons involved in said use. All statements or suggestions are made without warranty, express or implied, regarding accuracy of the information, the hazards connected with the use of the material or the results to be obtained from the use thereof.